Labedz et al.. SN 09/592,686 11/11/2005 SYSTEM AND METHOD FOR MANAGING MAINTENANCE... Greer, Burns & Crain, Ltd., Roger D. Greer (312) 360-0080 Our File 2014.63689 Sheet 8 of 30 REPLACEMENT SHEET



FIG. 8

细TangoPoint.com	₩ Weekly Inspection Form ✓
Inspections Inspector Facility Manager Building KSOPHF Address 6200 Sprint Parkway, Overland Location 1st Floor Date 6/6/2000 Inspection Weekly Type Start Inspection Exit	Add/Edit Close Flood Service Inspection Signage, prices, labels correct and pr Flood preprepartion surfaces clean: Flood preprepartion s
(a)	(b)

遡Weekly Inspection Form		
Save	Cancel	
Food Service Inspection		
Signage,prices,labels correct and		
Question 1 of 6 Poor		
9.0-10.0 = Good 6.0-8.0 = Satisfactory		
3.0-5.0 = Marginal 0.0-2.0 = Poor		
Rating 2 🕒 🕒		
Comments: Corrective Action		
Direction Lewis Hall □ Room 1		
What	Carpet	
Action	Spot Clean ▽	
Notes	Remove the Stains	

Ŋo	tes	
☐ Ma	ail this as an attachment	
To	John@ABCcleaningco.com	\triangledown
<u>C</u> c	John@ABCcleaningco.com	\neg
<u>S</u> ub	Carpet cleaning in Lewis Hal	l
	We would like to he carpet in Lewis ean and get rid of the	Δ
4		₽
Sa	<u>'e</u>	lose

(c)

(d)